

LOCATIONS WHERE CONTAMINATION WAS DETECTED
IN FLOODPLAINS AND SEDIMENTS EASTLAND WOOLEN MILL SITE
IN ECOLOGICAL STUDY AREAS (ESUs) 1—3 CORINNA, MAINE

FIGURE 7
LOCATIONS WHERE CONTAMINATION WAS DETECTED
IN FLOODPLAINS AND SEDIMENTS IN ESUS EASTLAND WOOLEN MILL SITE
4-6 AND UPPER PORTION OF ESU 7 CORINNA, MAINE

53648\c53648f2-7.dwg Wed, 15 May 2002 - 11:22am jpl



